


---

---

Series NXT3000 Yoke Assembly Kit  
North American Cylinders  
Chlorine, Sulfur Dioxide - 19469  
& Ammonia - 22325



---

---

**Cylinder Mounting Kit - Domestic  
For Chlorine and Sulfur Dioxide Service  
Complete Kit (Less Gasket, G-111) 19469**

<u>Key</u>	<u>Qty.</u>	<u>Part Description</u>	<u>Part Number</u>
1	1	Screw, Yoke	N-140
2	2	Nut, Hex: 7/16 -20	N-108
3	1	Plate, Yoke	T-188-1
4	1	Bar, Slide	19468
5	2	Stud	14415-1
+6	1	Gasket, Lead (See Note 1)	G-111
+Indicates Recommended Spare Parts			

**Cylinder Mounting Kit - Domestic  
For Ammonia Service  
Complete Kit (Less Gasket, G-111) 22325**

<u>Key</u>	<u>Qty.</u>	<u>Part Description</u>	<u>Part Number</u>
1	1	Screw, Yoke	N-140
2	2	Nut, Hex: 7/16 -20	N-108
3	1	Plate, Yoke	T-188-1
4	1	Bar, Slide	404C055U02
5	2	Stud	T-160-1
+6	1	Gasket, Lead (See Note 1)	G-111
+Indicates Recommended Spare Parts			

**Note:**

1. Key 6, (lead gasket) not included in cylinder mounting kit. Use the following Preventative Maintenance Kits for part: Inlet Valve Filters & Lead Gaskets (10 each) P/N 614S091U01 and Lead Gaskets (25 each) P/N BM-4901.
2. Lead Gasket (G-111) must be replaced every time the vacuum regulator is attached to a replacement gas cylinder. It is recommended that a supply of lead gaskets be carried in stock - **DO NOT USE SUBSTITUTE MATERIALS UNDER ANY CIRCUMSTANCES OR USE TWO STACKED PREVIOUSLY USED GASKETS.**
3. Refer to Parts List 100.7604 for other available cylinder yoke assemblies by country group.

**USING PARTS OTHER THAN GENUINE DNWT PARTS:**

- **CAN RESULT IN MALFUNCTION OF THE EQUIPMENT AND POTENTIALLY CAUSE SERIOUS PERSONAL AND ENVIRONMENTAL HEALTH AND SAFETY HAZARDS**
- **WILL VOID YOUR EQUIPMENT WARRANTY**
- **WILL VOID YOUR LIABILITY CLAIMS TO DNWT**

**De Nora Water Technologies**  
3000 Advance Lane Colmar, PA 18915  
ph +1 215 997 4000 • fax +1 215 997 4062  
web: [www.denora.com](http://www.denora.com)  
mail: [info.dnwt@denora.com](mailto:info.dnwt@denora.com)